


DESCRIPTION

DATE: 18 April 2007
 SUBJECT: LO Linx - Addition of Function Delay

- The purpose of this Bulletin is to inform technicians of the added Function Delay to the LO Linx Module.


INSTALLATION

1 Check Function on LO Linx Module



$F_d = 0$ to 10

Bodyguard
 Bodyguard III



F_d **Function Delay** - Allows user to adjust extra lockout time if needed for Bodyguard when door is closing. Adjustable from 0 - 10 sec.

NOTE: Only used when Bodyguard comes on before door is completely closed.

COMPANY CONTACT

Do not leave problems unresolved. If a satisfactory solution cannot be achieved after troubleshooting a problem, please call BEA., Inc. If you must wait for the following workday to call BEA, leave the door inoperable until satisfactory repairs can be made. Never sacrifice the safe operation of the automatic door or gate for an incomplete solution. The following numbers can be called 24 hours a day, 7 days a week. For more information, visit www.beasensors.com.

| | | | | | |
|-------------|----------------|----------------|----------------|-------------|----------------|
| West: | 1-888-419-2564 | US and Canada: | 1-866-249-7937 | North-East: | 1-866-836-1863 |
| South-East: | 1-800-407-4545 | Mid-West: | 1-888-308-8843 | Canada: | 1-866-836-1863 |